

Dryer Vent Service Report

Example Vent Service - Fictional

Property / job: Example property - not a real address

Visit date: 2026-10-10

Customer / contact: Example customer - fictional

Technician: Example technician - fictional

Report number: DEMO-20261010

Dryer / unit / termination: Electric dryer; exterior-wall termination

VISIT OUTCOME

Completed

ACCESS / VISIT LIMITS

Accessible connection and exterior outlet inspected. Concealed sections outside the visual scope.

INSPECTION

Inspected within recorded scope

FINDINGS

Fictional example: lint visible at the exterior damper; accessible connection attached. Concealed sections not visually inspected.

WORK PERFORMED

Fictional example: removed lint from the accessible vent run and termination; reconnected the accessible dryer duct; recorded an after reading.

AIRFLOW

Before: 80 CFM

After: 160 CFM

Context: Invented readings, not expected results or safety thresholds. Exterior outlet, same meter and dryer setting before and after.

CUSTOMER ACKNOWLEDGMENT

Acknowledgment recorded by report author

Fictional example: Example customer reviewed the record verbally at 16:00. No real acknowledgment or signature was collected.

RECOMMENDATIONS / NEXT STEPS

Fictional recommendation: keep the exterior termination clear. An illustrative next visit was agreed at the fictional customer's request; no universal interval is implied.

SERVICE RECORD

NEXT-SERVICE DATE

2027-10-10


RECORD LIMITS

This report records user-entered observations and work for this visit. It does not certify safety or code compliance, describe uninspected components, or guarantee future performance. Customer acknowledgment records the interaction; it is not a safety certification or a captured digital signature.

Visit photographs


Photos and captions supplied by the report author.

BEFORE



Before illustration for a fictional completed visit. No customer photograph or actual service evidence.

AFTER



After illustration for a fictional completed visit. No customer photograph or actual service evidence.