

Dryer Vent Service Report

EXAMPLE — NOT A REAL VISIT · Oct 9, 2026

service@example.com

Fictional service area

Customer & property

Example Customer — Fictional

Example Property (not a real address), ,

customer@example.com

Service details

Technician: Example technician

Dryer: Electric · Termination: Exterior wall

Airflow measurements

BEFORE	AFTER	CHANGE
80	160	+100%
CFM	CFM	relative to before

Measurement location / method: Fictional example: exterior termination, same instrument and dryer setting. Blank readings mean not measured.

Inspection findings

Termination · Concern observed

Fictional observation: visible lint at damper.

Addressed during this visit

Vent run · Not inspected

Fictional example: concealed sections not visually inspected.

Work completed

- Brush and clear the vent run
- Run dryer and check airflow

Technician notes

FICTIONAL EXAMPLE. Readings and work are illustrative, not measured or performed. No customer photographs or signatures are included. A real visit requires its own evidence.

Recommendations

Example: review the termination at the next visit. This is not a safety certification or a maintenance interval recommendation.

Recommended next service: Not scheduled

Customer acknowledgment

Acknowledgement unavailable: Fictional example: customer not present; no acknowledgement collected

Acknowledges receipt of the documented service information.

Prepared with VentProof. This report documents the technician's observations and work on the service date; it is not a safety certification or a guarantee of future performance. Recommendations depend on use and site conditions.